

Annexure D

BUILDING SAFETY CERTIFICATE

No. D 060/22/1

Dated: 27/06/2025

It is Certified that existing building **Sneha Prograssive School** at H.No: 8-156, 8-157, Chandur Mandal & Municipality, Nalgonda District-508255 is having 2 blocks with 2 Floors each block.

Details of Blocks(s) in School	Block (1)	Block (2)
No of Floor(s) in the Block	G+2	G+2

This building owned is owned/Occupied by **T. Arogyamma/ Sneha Prograssive School** have Complied with the Building safety requirements in accordance with National Building Code Rules and Verified by the officers concerned of **D. SRINIVAS RAO , Civil Engineer** on 24-06-2025 in the presence of Principal, Sneha Prograssive School, H.No: 8-156, 8-157, Chandur Mandal & Municipality, Nalgonda District-508255 and the building/Premises is fit for occupancy for running school with effect from 27-06-2025 for period of 1 year in accordance with rule and subject to compliance of the specific condition are appended.

Certified that Structure of the Building Sneha Prograssive School **Recognition No.2940 /A4/2017 Dated 30-10-2017** H.No: 8-156, 8-157, Chandur Mandal & Municipality, Nalgonda District-508255 is inspected on 24th JUNE 2025 and Found to be safe and structurally Stability.

Containing Ground+2 Floors.

Has been designed confirmed to is 456-2000 codes

The building will be stable and safe.




D. SRINIVASA RAO
B.Tech.(Civil)
Dimpul Architects & Engineers
Nuda Licensed Engineer
L.No: 2325/NUDA/PLG/LPT/2023
Mushampally Road, NALGONDA.

Name : **D. SRINIVAS RAO**

Designation: Civil Engineer

Name & Address of Department

Dimpul Architects & Engineers

Nuda Licensed Engineers

Mushampally Road, NALGONDA-508001

LIC NO: 2325/NUDA/PLG/LPT/2023.